Vehicle details

To vehicle | Current auction

Catalogue number: 92

... 88 89 90 91 92 93 94 95 96 97 ...

Ford Mondeo 2,0 TDCi
2.0 Litre,
Diesel,
6-gear manual transmission,
Diesel particle filter

Category:	Saloon, Number of doors 4
Emission class:	Euro 6
Fuel type:	Diesel
CO2 emissions (in g/km combined):	112
Power output:	110 KW / 150 HP
First registration:	09.2015
Federal Motor Transport Authority (KBA) Key Manufacturer:	8566
Federal Motor Transport Authority (KBA) Key Type:	BJA
Vehicle Identification Number:	WF0EXXWPCEF******
Transmission:	6-gear manual transmission
Colour:	grey Metallic
Colour name:	magneticgrau metallic
Read mileage:	**154.100 Kilometres**
Total number of owners:	1 Owner / 1 Entry / Entries
Vehicle origin:	Leasing vehicle
Supplier:	Alphabet Fuhrparkmanagement GmbH
Location:	D-65462 Ginsheim-Gustavsburg Germany
Vehicle release:	Release of the vehicle will take place at the earliest 3 working days following receipt of payment.
Vehicle documents:	
Type of ownership certificate:	Motor vehicle registration certificate (part II)
Sending of vehicle documents:	The sending of the Motor vehicle registration certificate (part II) will take place at the earliest 5 working day(s) after receipt of payment.
Vehicle document	Gemau Preisliste

Vehicle extras, add-ons and accessories

- ABS
- Airbags:6
- Automatic dimming internal mirror
- Automatic tailgate
- CD, DAB
- Climatronic
- Cruise control
- Diesel particle filter
- Electric windows front and rear
- Fog light
- Heated windscreen
- LED headlights
- Leather steering wheel
- Multi-function steering wheel
- Navigation (ex works): Ford Sync
- On-board computer
- Panorama sunroof
- Parking aid: ex works (front, rear)
- Power steering
- Remote central locking
- Reverse camera
- Side mirror electrically foldable
- Stability program: ESP
- Start/Stop system
- Sunblinds rear doors
- Tyre Pressure Indicator TPI

Extras Ford

handling

Number of keys:	2
Customer service information:	Service record available.
Latest inspection at:	11.2018 150.665 Kilometres
Last inspection at:	All inspections performed at a manufacturer-authorized workshop.
Next general inspection (HU) due:	09.2020 , technical inspection report is available
Exhaust gas inspection until	09.2020 , exhaust gas inspection (AU) report available
Starting price:	9.700 €
Tax:	Including 19% VAT

Demurrage charges:

Starting on 17.12.2018 the daily demurrage for this item will be 6,00 EUR net, plus VAT

Accident / Prior damage

Repaired previous damages:
09/2018 sill right - *Please note! This text was translated by machine!*
Damage amount: 200 EUR Net

• Business package 2 • Comfort package

Vehicle extras, add-ons and accessories

Active City
Winter II Paket
Ausparkassistent

Seats

• Number of seats: 5
• Alcantara leather: black
• Centre armrest: front

	Driver's seat	Front seat passenger	Rear left	Rear right
Seat heating	●	●	●	●
Electric seats	●	●		
Memory	●			
Lordosis	●	●		

General information

Fahrzeug wird im IST-Zustand angeboten!

View of instrument panel

Additional information

Service record

Service record

View of sat-navs

Details

Status report / Identified defects

Tires / Rims / Hub Caps

Tyre type: Winter tyres Alloy wheels: 16 Inches

	Tyres					Rims		Hub caps	
	Profile depth	Dimension	LI	DOT	Porous	Torn	Flat	Damaged	Scratch	Damaged	Missing
Left front	1 mm										
Left back	3 mm										
Right back	3 mm										
Right front	1 mm										

Second set of wheels

: Summer tyres Alloy wheels: 18 Inches

	Tyres					Rims		Hub caps	
	Profile depth	Dimension	LI	DOT	Porous	Torn	Flat	Damaged	Scratch	Damaged	Missing
Left front	4 mm							●			
Left back	3 mm								●		
Right back	3 mm								●		
Right front	4 mm								●		

Stone hits / Windscreen	Damaged	Minor stone chip damage	Major stone chip damage	Crack	Replacement recommended	Picture
Windscreen		●	●		●	
Windscreen		●	●		●	



Body	Damaged	Scratch	Dent	Rust	Repainted	Picture
Traces of impact on door edge back left		●				
Left back side section		●				
Rear left bumper		●				
Right back side section			●			
Traces of impact on door edge front right		●				
Bumper front centre		●				



More body photos:	Einstieg hinten rechts Kratzer/Delle	
Please note! Those texts were translated by machine!	Einstieg hinten rechts Kratzer/Delle	



Interior	Damaged	Wear	Stains	Burn	Picture

Driver's seat



Driver's seat



More interior photos:

Please note! Those texts were translated by machine!

Rollo Panoramadach öffnet nicht richtig

Vehicle collection

Please agree a date by telephone with your contact at the site before you collect a vehicle, stating the internal vehicle number. You can find this on the collection note or on your invoice.

Please note

All vehicles may have additional defects due to wear, mileage or age! (e.g. defect battery, oil leaks, paint defects, repaints, stone chip damage, ...) A road test and a viewing of the vehicle's underside were not carried out.

Missing parts and accessories must be replaced at buyer's own expense.

Close window | Tracking | Print